


CONTROL UNIT LUBRICATION MONITORING CCMon10

Art.nr. 907434

USER'S MANUAL



CONTENTS

1. DESCRIPTION	page. 2
2. DATA	page. 2
3. HANDLING	page. 3
4. TROUBLESHOOTING	page. 7
5. ELECTRIC WIRING DIAGRAM	appendix. 1
6. CE document	appendix, 2

1. DESCRIPTION

The control unit CCMon10 control the function of central lubrication systems.

Up to 10 flow meters can be connected to the control unit for monitoring the grease amounts.

FUNCTIONS

- Pre set grease amount, lubrication interval and alarm limits.
- All settings are protected by pass word.
- Control via the lubricated machine.
- Output for operation indicator.
- Output for alarms, issuing alarms at too low or too high grease flow.
- Possibility to choose between NO eller NC contact for the control from the lubricated machine, run/stop.

DEFINITIONS

Lubrication interval The time between the start of two lubrications.

Channel Part of the lubricated machine with separate run/stop contact.

2. DATA

Enclosure classification IP 65

Dimension 400x310x180 (BxHxD)

Weight 10 kg.

Power supply 100 - 120 V AC 3.3 A

200 - 240 V AC 2.0 A

50/60 Hz

Outputs: Max load 80 VA resistive load

100 W inductive load

Alarm output Voltage-free closing contact Operation indicator Voltage-free closing contact

Setting range Lubrication interval 1 - 32767 minutes

Grease amount 1 - 32767 cm³

3. HANDLING

MAIN MENU

*** MAIN MENU ***
LUB. INFO
SETTINGS
START STOP

Change to main menu: Press: Home

LUB. INFO
SETTINGS
ALARM
START STOP

Move up and down in the main menu: Press: up or down arrow

Starting and stopping the control unit: In the main menu, press F2 to start, F4 to stop.

PASSWORD

To make it impossible for any unauthorised persons to change the settings for times and pressures, these have been password-protected. To gain access to the settings, press F1 on the main menu – then this is displayed:

Password:

Key in the password (on delivery, this is 1234) and press: Enter

The following will then be displayed for a short time:

Level is 1

The settings can now be changed.

To change the password, press F5 (in the main menu)- the following is displayed:

Level 1 :1234

Key in the new password as required, and press: Enter

If the keyboard is not used for 1 minute, the following is displayed:

You are logged out

The settings are then protected once more.

SUB-MENUS

To reach the required sub-menu:

Place the cursor on the row containing the desired sub-menu using: up or down arrow and press: Enter

LUBRICATION INFORMATION

First choose for which lubrication point you want information about.

```
** LUB. INFO **
LUB. POINT 1
LUB. POINT 2
LUB. POINT 3
```

Place the cursor on the row containing the desired lubrication point using: up or down arrow and press: Enter

Information about the choosen lubrication point is shown:

```
** LUB. POINT 1 **
10 CM3 / 82 MIN
23 CM3 / 180 MIN
25 CM3 SET
875 CM3 THIS WEEK
1295 CM3 / WEEK
269875 CM3 TOTAL 0
3486952 CM3 TOTAL
ACTIVE
```

In this case lub. point 1 has got 10 cm³ during the 82 minutes that has passed of the current lubrication interval.

During the previous interval (180 min.) 23 cm³ was obtained.

The set value is 25 cm³.

875 cm³ has been obtained up to now this week.

1295 cm³ was obtained previous week.

269875 cm³ has been obtained since the resetable counter was reset.

3486952 cm³ has been obtained sice the system was started.

To reset the upper counter, place the cursor on that row with: up or down arrow, press 0 and Enter

ACTIVE tell that the lubrication point is activated.

MACHINE STOP tell that the lubrication point belongs to a machine stopped channel. SHUT OFF tell that the lubrication point belongs to channel 0, i.e. the lubrication point is not in use.

SETTINGS

Before the settings can be changed you must be logged in, see part Password.

First choose for which lurication point the settings shall be changed or if the settings for the machine control contact shall be changed under SETUP.

```
** SETTINGS **
SETUP
LUB. POINT 1
LUB. POINT 2 +
```

Place the cursor on the selected row with: up or down arrow and press: Enter

If some of the lubrication point was choosen the settings for the lubrication point is shown:

SETT	INGS LUB.P. 1
25	AMOUNT CM3
180	INTERVAL MIN
50	ALARM. MAX
20	ARARM MIN
1	CHANNEL

Place the cursor on the selected row with: up or down arrow, type in the value and press: Enter

SETTI	NGS LUB.P. 1
25	AMOUNT CM3
180	INTERVAL MIN
50	ALARM. MAX
20	ARARM MIN
1	CHANNEL

AMOUNT

Set the amount per interval in i cm³. Only even multiples of the amount that the flow meter gives per pulse can be set. If e.g. 3.2 is set the value automatically becomes 3,3

INTERVAL

The lubrication interval in minutes.

ALARM LIMIT MAX

Set the amount that shall be exceeded to obtain a high flow alarm.

ALARM LIMIT MIN

Set the amount that the actual amount shall be below to obtain a low flow alarm.

CHANNEL

Set which channel the lubrication point shall belong to. This controls which machine steering input that shall control this lubrication point, there are four machine steering contact = four channels. Set the channel to 0 if the lubrication point isn't in use.

SETTINGS FOR THE MACHINE CONTROL INPUTS

If the SETUP alternative was choosen the following is shown:

***	SET	***	
Open	when	running	C1
Open	when	running	C2
Clos	when	running	C3


This show that the machine control contacts for channel 1 and channel 2 shall be open when the machine is running. The machine control contacts for channel 3 shall be closed when the machine is running.

To change the settings for the channels:: Place the cursor on the row whith the selected channel with: up or down arrow and press: Enter

Then place the cursor on the selected choise and press SELECT (F2).

ALARM

Alarm events are listed on this screen, which can also be reached by pressing: Alarm



The upper alarm shows that the amount for lubrication point 1 during the interval was below the min alarm limit. The lower alarm shows that the amount for lubrication point 2 during the interval was above the max alarm limit

The alarms list stores the last 99 alarm events. To remove an alarm from the alarms list, place the cursor on the alarm required using: up or down arrow and press: left arrow

To find out the time when an alarm occurred, place the cursor on the alarm required using: up or down arrow and then press F4 (TIME).

Press F3 (+) to adjust the text size.

MACHINE INTERLOCKING

** LUB. POINT 1 **

10 CM3 / 82 MIN

23 CM3 / 180 MIN

25 CM3 SET

875 CM3 THIS WEEK

1295 CM3 / WEEK

269875 CM3 TOTAL 0

3486952 CM3 TOTAL


MACHINE STOP

When the contact for the machine locking is operated, the time calculation stops, to restart once the contact has been made again. The 'Machine stop' light on the front of the central control unit will be lit during a machine stop.

At the botton of the meny for lubrication information MACHINE STOP is shown for the lubrication points that belongs to the machine stopped channel.

ALARM ACKNOWLEDGEMENT

When an alarm has occurred, the alarm screen is displayed:



The asterisk (*) shows which alarm has not been acknowledged. Acknowledgement is carried out by pressing Ack.

The alarm output returns to the normal status.

In cases when two alarms have occurred at the same time, and only one has been acknowledged, a \$ sign will be displayed in the alarms list for the unacknowledged alarm. The \$ sign is also acknowledged by pressing F2 (ACK).

OPERATION INDICATOR

The output for operation indicator is closed when the control unit is in operation.

4. TROUBLESHOOTING

PROBLEM

The display is on but the central control unit cannot be started using F2. The display is off and the PLC power-lamp is on.

The display is on and the PLC power-lamp is off.

The display is off and the PLC powerlamp is off.


REMEDIAL ACTION


Check that the PLC is in RUN mode.


Check the fuse on the mains power unit. Next, check whether any power is being supplied to the operator panel to find out if the mains power unit or the operator panel are faulty. Check the 230 V supply to the PLC.


Check that power is being supplied to the central control unit and that the fuse on the central control unit has not blown.

When ordering spares, always give the serial number for the central control unit.









	1	2		3		4		5	6		7	8	9		10
•	WIRE				вох		COND	CONNECTING POINT	A		COND	CONNECTING POI	NT B	NOTE	,
A	Ledning	Cable No	Part No	Reference	Con. Block	Reference	WAY	Component	Socket	Reference	WAY	Component	Socket	1,10,12	
[``[-S 3-COND		1		L1			CENTRAL						POWER SUPPLY	
			2		N			GROUP						50 Hz MAX 10	A
L			3		J										
Τ.															
	-U 3-COND		1		401			PULSE TRANSDUCER 1	SIGN						
			2		+				+24V						
В			3		-				-24V						
ŀ	-U 3-COND		1		402			PULSE TRANSDUCER 2	SIGN						
ŀ	0 0 00115		2		+			T GEGE THAT THE SECOND EN	+24V						
一			3		<u> </u>				-24V						
f															
Ī	-U 3-COND		1		403			PULSE TRANSDUCER 3	SIGN						
c[2		+				+24V						
			3		_				-24V						
		1	1	1	1.5			DUI OF TRANSCOSTS	1						
	-U 3-COND	-	1	1	404			PULSE TRANSDUCER 4	SIGN						
			2		+				+24V						
ŀ			3		-				-24V						
_	-U 3-COND		1		405			PULSE TRANSDUCER 5	SIGN						
P	-0 3-COND		2		+			TOUSE MANAGEOREK S	+24V						
ŀ			3		† <u>-</u>				-24V						
f															
一	-U 3-COND		1		406			PULSE TRANSDUCER 6	SIGN						
			2		+				+24V						
			3		-				-24V						
Εļ															
-	-U 3-COND		1		407			PULSE TRANSDUCER 7	SIGN						
ŀ			2		+				+24V -24V						
ᅪ			3		+				-24V						
}	-U 3-COND		1	+	408			PULSE TRANSDUCER 8	SIGN						
-	0 0 00110		2	1	+			. I LOZ	+24V						
F			3	1	<u> </u>				-24V						
<u> </u>															
	-U 3-COND		1		409			PULSE TRANSDUCER 9	SIGN						
			2		+				+24V	·					
一		1	3	1					-24V						
-	11.7.00115	-	1	1	44.0			DUI CE TRANSPUGED 10	01011						
ŀ	-U 3-COND		1		410			PULSE TRANSDUCER 10							
G		+	3	+	+				+24V -24V						
}			1	1	+ -				-24v						
	-U 2-COND		1	+	411			MACHINE STOP 1							
ŀ	0 L 0011D		2	1	412										
						<u> </u>	Filename: 900	015-02		1001	ALUB AB		1	Proj.no. Sh 90015 5	eet Cont.
						Г	Designed by:	+46(0)120-812 0	0 00400	10 AD			90015 5 Drawing no	501 502
							Drawn by:	www S	.novael.s	e No 90				90015-02	
						Г		NOVALL			DIAGRAM			Customer referens 32603	
Date: 20100830 WIRING DIAGRAM									132003	-					

<u> </u>	1	2		3		4			6		7	8	9	10
	WIRE	Т			вох	1	COND	CONNECTING POINT	Α		COND	CONNECTING POINT	В	NOTE
	Ledning	Wire No	Part No	Reference	Con. Block	Reference	WAY	Component	Socket	Reference	WAY	Component	Socket	
	-U 2-COND		1		413			MACHINE STOP 2						
L			2		414									
L					115									
H	-U 2-COND		1		415 416			MACHINE STOP 3						
H			2		416				+					
H	-U 2-COND		1		417			MACHINE STOP 4						
	0 2 00.15		2		418									
	-U 3-COND		1		419			ALARM	С					
_			2		420				No					
_			3		421				Nc					
_	-U 3-COND	+	1		422			OPERATION INDICATION	+					
Г	-0 J-COND	+	2		423			OFERATION INDICATION	No					
r		1	3		424				Nc					
- 			1											
					425									
					426									
					427									
_					428 429									
_					430									
					+30									
_									-					
-									1					
_		+												
		1							1					
_		1					-		1					
		+							1					
_		+							+					
H														
							Filename: 900	015-02		ASSA	LUB AB	}		Proj.no. Sheet Con 90015 502 -
								/S +46(0)120-812 (.novael.s	CCMon	10	•		Drawing no
							Designed by: \	/S www	.novael.s	110 907	7434			90015-02
								/S NOVAEL 00830			DIAGRAM			Customer referens 32603 -